

Figure 1.




Figure 2. Fringe pattern distribution formed by the shear stress sensor optical assembly.




Figure 3. Fabrication sequence.




Figure 4